

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0792/1

Work Order Type: Weatherization

Audit Name: 80008KN0792-Audit

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0792

Alt. Client ID: KNOX

AGENCY INFORMATION

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & Licens	e Number:
Contractor's Signature:	

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Home built in 1985

Client Name:

Client ID: 80008KN0792 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0792/1

Report Run On: 5/8/2010

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 11

Measures

		ouble Pane Replacement (eet) e1	10 Squai	re	Componen	ts		1	Inspected
C		r to Appendix A- Standards f Guide.	or Weath	erizati	on Materials	and So	utheast		
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Double Pane Replacement (10 Square Feet)	Each	1					
		Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
(Other Detail								
Γ	A TO A SET OF								
•				Measu	re Sub Total:			Sub Total:	
	Field Notes:	,						and to construct on the second	
ŀ									

Page 2 of 11

ı	Measure 2 Mast	tic/Insulate Supply Bo	ot(QTY 9)		Componen	ts	***************************************	***************************************	Inspected
C	of boot v be insula cell foam Living R Living R KitchenS	upply2.2 pply2.2 pply2.1	to be caulk to R-6. This	ed with	n appropriate	caulk. B	oots to)	
	Bannes	app://2.2			Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Mastic/Insulate Supply Boot	Each	9				**************************************	Marine and a property of the first state of the state of
2	Labor	Labor	Each	9	and opposite the state of the s		***************************************		
c	Other Detail								
				Measur	e Sub Total:		S	Sub Total:	
	Field Notes:		.,,,,,,						

1	Measure 3 Return Box					Componen	ts			Inspected
C	Comment	Liquid M box whe Minimun Weather	oox made of 28 gauge glastic to be applied to re re it meets return regis n. No changes allowed rization Materials and S Appendix A- Standard lide.	eturn box to ster with appi . Refer to Ap Southeast Fie	seal a opriat pendi eld Gu	ll seams. Se e caulk. Inst x A- Standar ide. No cha	eal front ulate with ds for anges al	of returr n R-6 lowed.	า	
						Estimated			Actual	
#	Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construc	tion Mate	Return Box	Each	1			-		
2	Labor		Labor	Each	1			- Commonwealth		
	Other Detai									
					Measur	e Sub Total:			Sub Total:	
	Field Note	es:								

Measure 4 DWH Pipe Insulation	n		Component	ts		ı	nspected
Comment							
			Estimated			Actual	
# Material / Labor Description / Con	nment Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation DHW Pipe Insula	ntion Each	1					
Includes labor co corners must be properly. Refer to Appendix A- Star for Weatherizatio Materials and So Field Guide.	cut o ndards n						
2 Labor DHW Pipe Insula	tion Each	1					
Other Detail							
	,	Measu	e Sub Total:			Sub Total:	
Field Notes:							

DOE Weatherization Assistant Version 8.6.0

Report Run On: 5/8/2010

i	Measure 5 DWH	Tank Insulation			Componen	ts			Inspected
С	omment				Estimated	· .		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Tank Insulation	Each	1					
		extend pressure relief pipe as needed							
(Other Detail			,	1 [] [] [1
L									
		1411,000		Measu	e Sub Total:	-		Sub Total:	
	Field Notes:								

Page 6 of 11

1	Measure	6 D	uct Insulation			Componen	ts			Inspected
С	omment	tape.	ation must be a minimun No changes allowed. Re ials and Southeast Field	fer to Appen	idix A-	Standards fo	or Weath insulati	erizatio	n <i>Actual</i>	
#	Materiai /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulatio	n	Duct Insulation	SqFt	29.32			1	[
			Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southea Field Guide.							
2	Labor		Duct Insulation	SqFt	29.32					
C	Other Detai	,								
					Measur	Sub Total:			Sub Total:	
	Field Note	es:				-		-		

	Measure 7 CO N	Monitor is Needed			Componen	ts			Inspected
С	comment Refer to Field Gu	Attachment A- Standard	ls for Wea	ıtheriza	ition Materia	ls and So	outheas	st	
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.						,	
2	Labor	Labor	Each	1					
C	Other Detall								
								1	
				Measur	e Sub Total:		,	Sub Total: [
	Field Notes:		1.00.00						and the second s

	Measure 8 Fix	Any Other Heating Syste	m Probl	em	Componen	ts				Inspected
C	Must pe Amana Housing 1.5 ton thermos Thermo	es labor cost. Must be instant erform an ACCA Manual Jor Goodman 13 Seer Spling Director for approval), 10 Final size will be determinate. Must be equal to Honestat. Must be equal to Honestat (must submit equivalence client on operation of the	and subilit Heat Pu O KW emined by the leywell's leyth	mit witl amp (m ergend ne ACC PRO 4	n invoice. Mu nust submit e by heat. Size CA Manual J. 000 Program	ist be ed quivale is appro Install imable	qua nt i	al to to mately	,	
		•			Estimated				Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total		Qty	Unit Cost	Total
1	Unspecified	Replacement of Heating System (+)	Each	1	Terrament					
2	Labor	labor	Each	1]		
C	Other Detail									

				Measui	e Sub Total:	THE THE PARTY OF T		8	Sub Total:	
	Field Notes:								•	

ı	Measure 9 Fix I	mproper Venting (Clothe	s Dryer)	Component	ts			Inspected
С	protrudir is 15 fee	ents installed with damper ng through pipe. Must be v et. No changes allowed. R rization Materials and Sou	vented to lefer to A	outsio ttachr	de of home. N nent A- Stan	/laximun	ı length	1	
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1				The state of the s	
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
C	Other Detail								
				Measu	e Sub Total:] ;	Sub Total:	
	Field Notes:								

Client ID: 80008KN0792 Alt. Client ID: KNOX DOE Weatherization Assistant Version 8.6.0 Page 10 of 11

Report Run On: 5/8/2010

Measure 10 Fix Impro Exhaust F	per Venting of Bathr an(QTY 2)	oom		Componen	ts			Inspected
Comment Bath Vents in Attachment A Guide.	stalled to outside of he - Standards for Weath							
				Estimated			Actual	
# Material / Labor Desc	eription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Bath Outs	Vent w/ Piping to ide	Each	2					
Stan Wea	r to Attachment A- dards for therization Materials Southeast Field e.							
2 Labor Labo	or	Each	2					
Other Detail								

<u> </u>		1	Measur	e Sub Total:		 	Sub Total:	
Field Notes:				· ·				
		Work O	der Gra	nd Total:]	Grani	d Total:	

Client ID: 80008KN0792 Alt. Client ID: KNOX Work Order Name: WO/80008KN0792/1 Report Run On: 5/8/2010

Page 11 of 11